

Energy Auditor, Contractor, and Home Inspector Training

Don West

Instructor

Course Instructors:

Common Errors Venting Gas Appliances

Instructor: Don West

National Historic Preservation Act/Section 106

Instructor: W. Shay

REM Training

Instructor: B. Rotert

Course Description:

Common Errors Venting Gas Appliances

- Inspection of existing vents and chimneys
- Chimneys, vents, and common vents
- Common errors made when sizing vents and chimneys
- Manifolds, vent offsets, connectors, and extended length vent connectors
- Clearance to combustibles
- Masonry chimney kits and flex liners
- Exterior chimneys and 80% furnaces
- Software programs for vent sizing

National Historic Preservation Act/Section 106.

- Overview of the National Historic Preservation Act review requirements (Section 106 of NHPA) when Federal funds are involved.

REM Training

- Dual fuel heat pumps
- De-rating existing furnace and A/C units
- Insulating framed floors vs. basement walls
- Improvement cost libraries

June 16th, 2011

Brian Rotert

Special thanks to our utility partners:

Missouri Gas Energy

Atmos Energy

Kansas Gas Service

